

Computer Mode  
Surface Screen  
if no dive made yet

Computer Mode  
Surface Screen  
after a dive



- |                                                                              |                                                                                               |
|------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|
| 1 - Bluetooth icon flashing when ON and connected, solid when not connected. | 5 - Battery icon flashing in low battery warning<br>Empty shell flashing in low battery alarm |
| 2 - Surface time                                                             | 6 - Dive time of the last dive                                                                |
| 3 - Max. depth of the last dive                                              | 7 - Actual tissue loading (Ti bar)                                                            |
| 4 - Actual gas                                                               |                                                                                               |

- |                                                                                        |                               |
|----------------------------------------------------------------------------------------|-------------------------------|
| L short press to left button                                                           | R short press to right button |
| ⬇ long press to left button                                                            | ⬇ long press to right button  |
| L+R short press to both buttons at the same time: back to Surface Screen from anywhere |                               |

Computer Mode  
Surface Menu

PLAN  
LOGBOOK  
SETTINGS  
ALARMS  
DIVE SET.  
STATS  
OWNER  
DEVICE

No Deco or O2 Time Limits (NDL or OTL)

L to next depth

List of Dives  
(dates and #)

L to next dive

Depth, Start Time,  
Gas, Dive Time,  
Ti Bar, ASC Bar

Max Temperature,  
Min Temperature,  
Altitude Level

Max PO2 (max reached)  
OXTOX (end of dive)

Set Date, Time,  
Date Format,  
Time Format

Set  
Units

Set  
Bluetooth

Set  
Light Duration

Set  
Sound

Set  
Depth Alarm

Set  
Dive Time Alarm

Set  
No Deco Alarm

Set  
Oxtox Alarm

Set  
Dive Mode

Set  
Water Type

Set  
Sampling Rate

Set  
Gases

Set  
Conservatism

Set  
Safety Stop

Set  
Deep Stop

Max Depth, Number of Dives,  
Total Dive Hours, Min. Temperature

Name and Phone Number

Model, Serial,  
Firmware Version

Reset  
Deco

Gauge  
Mode  
Surface  
Screen



LOGBOOK  
SETTINGS  
ALARMS  
SET DIVE  
STATS  
OWNER  
DEVICE

Set  
Depth Alarm

Set  
Dive Time Alarm

Set  
Dive Mode

Set  
Water Type

Set  
Sampling Rate

Note:  
Other menus and info  
screens are the same as  
Computer Mode


- L to increase/change the value of a flashing setting  
⬇ (hold) to scroll  
⬇ Decrease/change the value of a flashing setting, decrease depth in Plan, go up in the Log list  
R to save

oceanpro




**SPiRiT**  
**QUICK**  
**REFERENCE**

## Computer Mode Dive Screen



|                                          |                                    |
|------------------------------------------|------------------------------------|
| 1 - Depth                                | 4 - Dive time                      |
| 2 - No deco time (or O2 Time if smaller) | 5 - Actual Gas                     |
| 3 - Ascent rate bar (ASC)                | 6 - Actual tissue loading (Ti bar) |

Note:  
TTS (Time to Surface)  
displayed if decompression  
stop(s) required.



Back to  
Computer Mode  
Dive Screen

SWITCH TO  
GAS 2


Switch gas and back to  
Computer Dive Screen

SWITCH TO  
GAS 3

Switch gas and back to  
Computer Dive Screen

Note:  
The gases that  
are OFF will  
not be displayed

Start dive if deeper than 5 ft (1.5 m)  
for 5 seconds. Exit from dive if  
shallower than 3 ft (0.9 m) for  
1 seconds. If you dive again in 10  
minutes after exiting from a dive,  
the dive will continue adding the  
surface time to the dive time.



Activate Backlight

Acknowledge  
alarm if any alarm  
is sounding



Safety stop will be  
displayed if set to ON  
and if depth exceeded  
30 ft (9 m) at depth  
and duration you set.



A 2-minute deep stop  
will be displayed  
if set ON and if depth  
exceeded 80 ft (24 m).




Note:  
During Deep and Safety stops  
No Deco time is added  
to Dive Alt 1.



If decompression stop(s)  
required, the deepest  
stop's depth and time  
will be displayed.

## Gauge Mode Dive Screen




START  
CHRONO

RESET  
CHRONO

STOP  
CHRONO

to start  
chrno again



Back to  
Gauge Mode  
Dive Screen

Notes:  
No decompression  
or oxygen toxicity  
related calculations  
in Gauge Mode.

Switch to Computer Mode  
blocked for 24 hours  
after a Gauge Mode dive.